

JET

JDBS-5-M

Belt & Disc Sander

10000470M ~230V 50Hz

PARTS LIST

JPW (Tool) AG

Tämperlistrasse 5

CH-8117 Fällanden

Switzerland

Phone +41 44 806 47 48


Fax +41 44 806 47 58

www.jettools.com



P- 10000470M 2017-11

JDBS-5-M Belt & Disc Sander – Exploded View



JDBS-5-M Belt & Disc Sander – Parts List

Index No.	Part No.	Description	Size	Qty
1	JDBS5-1	Screw and Flat Washer Assembly	M6x18	2
2	JDBS5-2	Rubber Feet		4
3	JDBS5-3	Screw and Flat Washer Assembly	M4x12	4
4	JDBS5-4	Baseplate		1
5	JDBS5-5	Base		1
6	JDBS5-6	Switch Baseplate		1
7	JDBS5-7	Screw	M5x10	2
8	JDBS5-8	End Shield		1
9	JDBS5-9	Wave Washer	Ø35	1
10	JDBS5-10	Capacitor	8uF/450V	1
11	JDBS5-11	Switch		1
12	JDBS5-12	Screw and Flat Washer Assembly	M4x8	2
13	JDBS5-13	Stator		1
14	JDBS5-14	rubber protection part		1
15	JDBS5-15	Power cord and Plug		1
16	JDBS5-16	Capacitor Support		1
17	JDBS5-17	Hex Nut	M8	2
18	JDBS5-18	Hex Nut	M6	1
19	JDBS5-19	Belt Protection Plate		1
20	JDBS5-20	Rotor		1
21	JDBS5-21	Screw	M4x8	1
22	JDBS5-22	Limit plate		1
23	JDBS5-23	Flat Washer	Ø4	2
24	JDBS5-24	Screw	M4x10	2
25	JDBS5-25	Locking Handle		1
26	JDBS5-26	Belt Protection Guard		1
27	JDBS5-27	Belt Support Cover		1
28	JDBS5-28	Sanding Belt 100#	1"x30"	1
29	JDBS5-29	Driven Wheel		2
30	JDBS5-30	External Circlip	D15	2
31	JDBS5-31	Bearing	6202-RZ	4
32	JDBS5-32	Driven Shaft		1
33	JDBS5-33	Screw	M6x8	1
34	JDBS5-34	Screw with Washer	M5x16-Left	1
35	JDBS5-35	Flat Washer	Ø4	2
36	JDBS5-36	Driving Wheel		1
37	JDBS5-37	Screw	M6x10	3
38	JDBS5-38	Hex Bolt	M10x25	1
39	JDBS5-39	Belt Support		1
40	JDBS5-40	Screw	M6x20	1
41	JDBS5-41	Belt Work Table		1
42	JDBS5-42	Flat Washer	Ø 8	1
43	JDBS5-43	Locking Handle Assembly		1
44	JDBS5-44	Shaft Guard		1
45	JDBS5-45	Spring		1
46	JDBS5-46	Hex Nut	M10	1
47	JDBS5-47	Fixed Plate		1
48	JDBS5-48	Spring		1
49	JDBS5-49	Adjustable Handle		1
50	JDBS5-50	Self-Tapping Screw	ST4.2x16	4
51	JDBS5-51	Cylindrical Pin	Ø3x20	1
52	JDBS5-52	Adjustable Shaft		1
53	JDBS5-53	Spring		1
54	JDBS5-54	Flat Washer	Ø 5	2
55	JDBS5-55	Split Washer	Ø 3.5	1
56	JDBS5-56	Vacuum connector		1
57	JDBS5-57	Guide		1
58	JDBS5-58	Lock Washer	Ø 4	1
59	JDBS5-59	Screw and Flat Washer Assembly	M4x6	1
60	JDBS5-60	Miter Gauge Knob		1

Index No.	Part No.	Description	Size	Qty
61	JDBS5-61	Hex Nut	M4	4
62	JDBS5-62	Miter Gauge		1
63	JDBS5-63	Mitre Joint pole		1
64	JDBS5-64	Disc Work Table		1
65	JDBS5-65	Flat Washer	Ø 6	2
66	JDBS5-66	Lock Handle		2
67	JDBS5-67	Screw with Washer	M4x8	3
68	JDBS5-68	Screw with Washer	M6x16	1
69	JDBS5-69	Lock Nut	M4	2
70	JDBS5-70	Disc		1
71	JDBS5-71	Disc End Shield		1
72	JDBS5-72	Screw and Flat Washer Assembly	M4x153	4
73	JDBS5-73	38mm Adapter		1
74	JDBS5-74	Screw	M4x12	2
75	JDBS5-75	Sanding Paper	5"	1
76	JDBS5-76	strain relief plate 1		1
77	JDBS5-77	strain relief plate 2		1
78	JDBS5-78	screw	M4x18	2
	JET-92	Jet Logo (not shown)	92x38mm	1
		ID Label (not shown)		1
		Motor Label (not shown)		1
		Warning Label (not shown)		1

Wiring Diagram for JDBS-5-M

10000470M..... ~ 230V, 50Hz

